



Experience is the solution

314 North Pearl Street ♦ Albany, New York 12207
 (800) 848-4983 ♦ (518) 434-4546 ♦ Fax (518) 434-0891

NVLAP#200552-0
 AIHA-LAP,LLCAccredited#100307
 NYSDOH#10709

Bulk Asbestos Report

NYS Thruway Authority - Albany Div.
 200 Southern Boulevard
 Bldg. 1
 Albany, NY 12209

Attn: ***AES IH Dept***

Project: Asbestos Services
ProjLocation: Malden Service Area

Date Sampled: 03/09/2016
Date Received: 03/09/2016

PLM Analyzed: 03/16/2016 by SW
TEM Analyzed: 3/15/2016 by tkh

Method References: NYSDOH ELAP 198.1/198.4/198.6

ReportDate: 3/16/2016

WorkOrder: 160309075

Lab ID	Sample Identification and Description	Materials Type	Non-asbestos Fibers (Percent and Type)	PLM Asbestos (Percent and Type)	PLM Result	TEM Result of Residue	Final Status
001 A	<u>01-Roofing Core</u> Homogeneous, White, Non-Friable Material 13.4 Wt % Remaining	Other		<1 % Tremolite(Trace)	<1% Inconclusive**	No Asbestos Detected	<1% NAC
001 B	<u>01-Roofing Core</u> Homogeneous, Black, Non-Friable Material 4.3 Wt % Remaining	Tar/Roofing		No asbestos detected	<1% Inconclusive**	No Asbestos Detected	<1% NAC
001 C	<u>01-Roofing Core</u> Homogeneous, Black, Non-Friable Material 6.8 Wt % Remaining	Tar/Roofing		No asbestos detected	<1% Inconclusive**	No Asbestos Detected	<1% NAC


Lab ID	Sample Identification and Description	Materials Type	Non-asbestos Fibers (Percent and Type)	PLM Asbestos (Percent and Type)	PLM Result	TEM Result of Residue	Final Status
001	D 01-Roofing Core Homogeneous, Black,Non-Friable Material 13.7 Wt % Remaining	Tar/Roofing		No asbestos detected	<1% Inconclusive**	No Asbestos Detected	<1% NAC
001	E 01-Roofing Core Homogeneous, Black,Non-Friable Material 0.1 Wt % Remaining	Tar/Roofing			<1% NAC	-----	<1% NAC
002	A 02-Roofing Core Homogeneous, White,Non-Friable Material 8.8 Wt % Remaining	Tar/Roofing		<1 % Tremolite(Trace)	<1% Inconclusive**	No Asbestos Detected	<1% NAC
002	B 02-Roofing Core Homogeneous, Black,Non-Friable Material 10.5 Wt % Remaining	Tar/Roofing		No asbestos detected	<1% Inconclusive**	No Asbestos Detected	<1% NAC
002	C 02-Roofing Core Homogeneous, Black,Non-Friable Material 3.5 Wt % Remaining	Tar/Roofing		No asbestos detected	<1% Inconclusive**	No Asbestos Detected	<1% NAC
002	D 02-Roofing Core Homogeneous, Black,Non-Friable Material 0.1 Wt % Remaining	Tar/Roofing			<1% NAC	-----	<1% NAC

Lab ID	Sample Identification and Description	Materials Type	Non-asbestos Fibers (Percent and Type)	PLM Asbestos (Percent and Type)	PLM Result	TEM Result of Residue	Final Status
002	E 02-Roofing Core Homogeneous, Black, Non-Friable Material 0.1 Wt % Remaining	Tar/Roofing			<1% NAC	-----	<1% NAC

ACM:Asbestos Containing Material


NAC:Non-Asbestos Containing Material

**A negative result for an NOB sample is considered inconclusive. The following NYS ELAP disclaimer applies: "PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. Before this material can be considered or treated as non-asbestos containing, confirmation must be made using transmission electron microscopy(TEM)".



Approved by: _____
Tara Daniels
Laboratory Manager

160309075



314 North Pearl Street
Albany, New York 12207
518-434-4546/434-0891 FAX

BULK SAMPLE DATA AND CHAIN OF CUSTODY RECORD

A full service analytical research laboratory offering solutions to environmental concerns

Client Name: <i>NYS Thruway Authority</i>	Address:	Date: <i>3/9/16</i>
Send Report To:	Project Name (Location): <i>Malden Service Area</i>	Project Manager: <i>George Bailey</i>
Client Phone No:	Project Number: <i>POF # 160307-EA T-2</i>	Inspector: <i>George Bailey</i>
Client Fax No:		

BULK SAMPLE INFORMATION

Lab Sample ID No.	Homogenous Area No.	Bulk Sample ID No./Material	SUR TSI MIS	Sample Location	Material Qty. (LF,SF)	Analysis Requested
<i>001</i>	<i>Flat Roof</i>	<i>01 - Roofing Core</i>	<i>M</i>	<i>NW Corner</i>	<i>1050SF</i>	<i>PLM/NOB</i>
<i>002</i>	<i>West side</i>	<i>02 - " "</i>	<i>M</i>	<i>SE Corner</i>	<i>"</i>	<i>PLM/NOB</i>

SAFE

Turnaround Time Request: <input type="checkbox"/> 1 Day <input type="checkbox"/> 3 Day <input checked="" type="checkbox"/> Normal <input type="checkbox"/> 2 Day <input type="checkbox"/> 5 Day <input type="checkbox"/> Other _____	Special Instructions/Remarks <i>Analyze distinct layers</i>
CC Report To:	
Relinquished by: (Signature) <i>George Bailey 3/9/16 @ 14:50</i>	Received by: (Signature) <i>Carmichael</i>
Relinquished by: (Signature)	Received for Laboratory by: <i>Carmichael</i>
	Date/Time <i>3/9/16 4:24 PM</i>

WHITE - Lab Copy YELLOW - Sampler Copy PINK - Generator Copy



Experience is the solution

314 North Pearl Street • Albany, New York 12207 • (518) 434-4546 • Fax (518) 434-0891

TERMS, CONDITIONS & LIMITATIONS

All service rendered by the **Adirondack Environmental Services, Inc.** are undertaken and all rates are based upon the following terms:

- (a) Neither **Adirondack Environmental Services, Inc.**, nor any of its employees, agents or sub-contractors shall be liable for any loss or damage arising out of **Adirondack Environmental Services, Inc.**'s performance or nonperformance, whether by way of negligence or breach of contract, or otherwise, in any amount greater than twice the amount billed to the customer for the work leading to the claim of the customer. Said remedy shall be the sole and exclusive remedy against **Adirondack Environmental Services, Inc.** arising out of its work.
- (b) All claims made must be in writing within forty-five (45) days after delivery of the **Adirondack Environmental Services, Inc.** report regarding said work or such claim shall be deemed or irrevocably waived.
- (c) **Adirondack Environmental Services, Inc.** reports are submitted in writing and are for our customers only. Our customers are considered to be only those entities being billed for our services. Acquisition of an **Adirondack Environmental Services, Inc.** report by other than our customer does not constitute a representation of **Adirondack Environmental Services, Inc.** as to the accuracy of the contents thereof.
- (d) In no event shall **Adirondack Environmental Services, Inc.**, its employees, agents or sub-contractors be responsible for consequential or special damages of any kind or in any amount.
- (e) No deviation from the terms set forth herein shall bind **Adirondack Environmental Services, Inc.** unless in writing and signed by a Director of **Adirondack Environmental Services, Inc.**
- (f) Results pertain only to items analyzed. Information supplied by client is assumed to be correct. This information may be used on reports and in calculations and **Adirondack Environmental Services, Inc.** is not responsible for the accuracy of this information.
- (g) Payments by Credit Card/Purchase Cards are subject to a 3% additional charge.